ISOLATED AREAS

Presented by Jim Cashdollar Seattle Aircraft Certification Office

Isolated Areas

- Isolated areas are becoming more commonplace
- Occur on Transport & Executive Aircraft
 - Purser Workstations
 - Crew Rest Areas
 - Private Bedrooms / Offices

Private Bedrooms and Offices

- We Will Focus on Three Aspects
 - Emergency Floor Proximity Lighting
 - Supplemental Oxygen
 - Smoke Detection

Floor Proximity Lights

- The requirement for a Floor Proximity Emergency Escape Path Lighting System (FPEEPMS) was implemented by § 25.812(e), Amendment 25-58
- Section 121.310(c)(3) requires a FPEEPMS for all transport aircraft certificated after January 1, 1958
- Part 25 requirements are applicable to both transport and executive aircraft

Floor Proximity Lights

- Regulation:
 - § 25.812(e) Floor proximity emergency escape path marking must provide emergency evacuation guidance for passengers when all sources of illumination more than 4 feet above the cabin aisle floor are totally obscured. In the dark of the night, the floor proximity emergency escape path marking must enable each passenger to--
 - After leaving the passenger seat, visually identify the emergency escape path along the cabin aisle floor to the first exits or pair of exits forward and aft of the seat; and
 - Readily identify each exit from the emergency escape path by reference only to markings and visual features not more than 4 feet above the cabin floor.

Floor Proximity Lights

- Guidance Material
 - AC 25.812-1A
 - · Powered systems
 - Incandescent
 - Electroluminescent
 - AC 25.812-2
 - Photoluminescent
 - Rules / guidance material were written around passenger configurations
 - Typified by rows of seats installed adjacent to the main aisle

Floor Proximity Lights

- Executive Interior Considerations
 - FPEEPMS must provide guidance to passengers located <u>throughout</u> the cabin interior
 - Isolated areas that can be occupied for TT&L must be evaluated
 - Passengers must be able to find their way to the main aisle using the FPEEPMS

Floor Proximity Lights

- Use of Floodlights (Exit Identifiers)
 - Floodlights have been used to guide passengers from an isolated area to the main aisle
 - Floodlights located near the doorway of the isolated area
 - Caution
 - Floodlights in the main cabin may provide a lot of light, but may not provide the guidance as a series of incandescent lights

Floor Proximity Lights

- Summary:
 - Design of a FPEEPMS system for executive interiors can be challenging, and somewhat controversial
 - Naïve subject tests may be required to validate the efficacy of the FPEEPMS
 - Close coordination with the project ACO is essential!

Supplemental Oxygen

• Regulation

Guidance

- § 25.1447

AC 25-17

- AC 25-17 addresses executive interiors, groupings of persons
 - Need to minimize the likelihood that a person will take the mask intended for another

Supplemental Oxygen

- Isolated Areas Considerations
 - Occupants must be aware that there is a need for supplemental oxygen
 - Automatic presentation of masks provides indication
 - Automatic presentation is ineffective if you can't see the masks drop
 - Transport configurations are somewhat reliant on crowd awareness; not necessarily provided in isolated areas

Supplemental Oxygen

- Mask Drop Awareness
 - Translating / swiveling seats require additional oxygen system design considerations
 - Occupants may not see masks drop because of seat orientation
 - Additional notification may be necessary
 - Aural
 - Visual

Supplemental Oxygen

- Accessibility
 - Oxygen must be accessible when occupants are seated and belted
 - Masks shouldn't be able to be donned without initiating oxygen flow
 - Design needs to consider couches transformed into beds, seats with very large recline, etc., and the accessibility / donning criteria

Smoke Detection

- Private bedrooms, offices and other areas in an executive interior are likely to be isolated by a door preventing early detection of a fire.
- If not immediately combated, a fire in such an isolated area could ultimately result in the loss of the aircraft.

Smoke Detection

- Pertinent Regulations
 - § 25.854 (Lavatory fire detection)
 - § 25.858 (Cargo or baggage compartment smoke or fire detection systems)
- Regulations don't completely address executive interior configurations

Smoke Detection

- Are smoke detectors required for isolated compartments?
 - YES! They are a requirement on transport
 AND executive interiors
 - Special conditions (747 crew rests)
 - Equivalent safety findings (777 lower lobe)
 - Methods of compliance (737-BBJ)

Smoke Detection

- Design Requirements for Smoke Detectors
 - Visual indication in the flight deck
 - Aural warning within the isolated compartment
 - Detection within one minute after the start of a fire, and at a temperature significantly below the point of structural degradation
 - Doesn't have to be a cargo compartment detection system

Smoke Detection

- Smoke detectors in isolated areas make good sense!
 - Include them in your certification plans

Presented by Jim Cashdollar Seattle Aircraft Certification Office

- Firm handholds are a requirement of Part 25
 - Regulation in effect at the adoption of Part 25 {§ 25.785(d)}
 - If the seat backs do not have a firm hand hold, there must be a hand grip or rail along each aisle to enable occupants to steady themselves while using the aisles in moderately rough air.
 - Regulation {25.785(j)} is essentially unchanged at Amendment 25-88

- Requirements apply to:
 - Transport Aircraft (i.e., airline revenue service)
 - Seats throughout the passenger cabin
 - Executive Aircraft (i.e., business jets)
 - No typical cabin configuration

- FAA Guidance
 - Reference AC 25-17
- Seat backs may serve as a firm hand hold
 - Many seats are capable of breakover
 - Breakover load must be adequate to be considered firm - minimum of 25 pounds resistance when applied at the top of the seatback

- Must be evaluated for both "expected" and "unexpected" turbulence
 - For unexpected turbulence, the distance between the handholds and the relative position of the handholds is crucial.

- Armrests aren't adequate
 - Too low typically around 24 inches off the ground
 - Acceptable height is 33 inches or more
- Stowage bins aren't adequate (typically)
 - Smooth surfaces nothing to grasp
 - Too high
 - Could be considered with an integrated rail

- Additional Considerations
 - Large seat pitches (up to 65 inches)
 - Large amounts of recline are typical
 - Seatbacks may still be used as handholds
 - Seatbacks become ineffective handholds when they are reclined below 33 inches above the floor

Handholds

• If the seatbacks are ineffective due to distance and/or height, supplementary features must be added!

- Additional Considerations
 - Very Large Pitch / Very Large Recline
 - Maximum spacing between handholds should not be greater than 65 inches
 - Supplementary features should be readily obvious and must be effective
 - » Additional bars / rails installed on seats have been accepted
 - » Knobs / posts installed on seats have not been accepted
 - » Handrails

- Executive Interiors
 - Handholds need to be evaluated throughout the passenger cabin
 - Supplementary features may be necessary due to distances between seats / other handholds
 - Long narrow corridors
 - May be acceptable provided there are means for the passengers to steady themselves
 - Close coordination with the project ACO is essential!